Office of the Assistant Executive Engineer, No.1 Buildings Sub Division, V.V. Centre Bangalore. 560 001



Phone: 080-22863305


E-mail: acelvvtower@gmail.com

PUBLIC WORKS DEPARTMENT

AN ISO 9001-2008 CERTIFIED DIVISION

No: AEE/No.1 Bld Sub Dvn/V.V. Centre /2024-25/

Dated:



BUILDING SAFETY CERTIFICATE

Certified that the existing building "NEW HORIZON INTERNATIONAL SCHOOL," at Hennur Main Road, Byrathi Village, Bengaluru - 560037. comprised of 2 Blocks that is Block-1 & 02 with 1 basement, ground floor and 4 upper floors in each block-owner/occupied by "NEW HORIZON INTERNATIONAL SCHOOL," at Sy. No. '115/1, Hennur Main Road, Byrathi Village, Bengaluru - 560037, have complied with the building safety requirements in accordance with National Building code Rules. The trust has taken necessary tests of Safety Check report, Physical observation, Investigating studies, Rebound hammer test, Ultra Sonic test report, Ultra Sonic pulse velocity test - by Hencon Associates, No. 274, 1st D Main Road, Kengeri Satelite town, Bangalore - 560060

The building verified by the officers concerned of Public Works Department, No. 1 Buildings Sub-division, V.V. Centre, Bangalore on **03-08-2024** in the presence of Principal and that the building/premises is fit for occupancy for running school with effect from **07-08-2024** for a period of **one year** in accordance with rule and subject to compliance of the specific conditions as appended.

- The school should take necessary certificates from Fire department and other competent authorities within the time.
- 2) Building should be maintained neatly using good materials and experts.
- 3) The school should follow necessary safety precautions of students & teachers.
- 4) In the time of any changes in the structure of school building the school should take permission from competent authority. Otherwise this certificate will get cancelled without any conditions.
- 5) The school should maintain neatly of drinking water facility, toilet neatness and other conditions from BBMP which are applied for schools and colleges.

Issued on: 07-08-2024

विकार्णी किल्लेहिकार क्षित्रेटिकार क्षेत्र क्षित्रेटिकार क्षित्रेटिकार क्षित्रेटिकार क्षित्रेटिकार क्षेत्र क्षे

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಹಾಗೂ Hencon Associates, No. 274, 151 D Main Road, Kengeri Satelite town, Bangalore - 560060 ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಗಳನ್ನು ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡದ ಆರ್.ಸಿ.ಸಿ. ಕಂಬ, ಕೊಲೆ ಹಾಗೂ ಛಾವಣಿಯಲ್ಲಿ ಯಾವುದೇ ಬಿರುಕುಗಳು ಕಂಡು ಬಂದಿರುವುದಿಲ್ಲ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ಫೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಹಾಗೂ ಕಟ್ಟಡವು Structural Sound ಕಟ್ಟಡವು ಮೇಲ್ಫೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುವುದರಿಂದ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ಫೋಟಕ್ಕೆ ನುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಈ ಕೆಳಕಂಡ ಪರತ್ರುಗಳನ್ನು ಅನುಸರಿಸಲು ಸೂಚಿಸಲಾಗಿದೆ.

- ಅಗ್ನಿಶಾಮಕ ಇಲಾಖೆ ಮತ್ತು ಇತರೆ ಸಂಬಂಧಪಟ್ಟ ಇಲಾಖೆಗಳ ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರಗಳಿಂದ ಅನುಮತಿ / ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನಿಯಮಾವಳಿಗಳ ಅನ್ವಯ ನಿಗದಿತ ಸಮಯಗಳಲ್ಲಿ ಪಡೆಯತಕ್ಕದ್ದು.
- 2. ಕಟ್ಪಡವನ್ನು ಕಾಲಕಾಲಕ್ಕೆ ಉತ್ತಮ ಗುಣಮಟ್ಟದ ಸಾಮಗ್ರಿಗಳನ್ನು ಬಳಸಿ ತಜ್ಞರಿಂದ ವ್ಯವಸ್ಥಿತವಾಗಿ ನಿರ್ವಹಣೆ ಮಾಡತಕ್ಕದ್ದು.
- 3. ವಿದ್ಯಾರ್ಥಿಗಳ ಹಾಗೂ ಶಿಕ್ಷಕರ ಸುರಕ್ಷತೆಗೆ ಸಕಲ ಆದ್ಯತೆಯನ್ನು ನೀಡಿ ಸೂಕ್ತ ಸುರಕ್ಷತಾ ವ್ಯವಸ್ಥೆಯನ್ನು ಅಳವಡಿಸಿಕೊಳ್ಳತಕ್ಕದ್ದು.
- 4. ಕಟ್ಟಡದ ಸದೃಡತೆಗೆ ಧಕ್ಕೆಯಾಗುವಂತಹ ಯಾವುದೇ ಇತರೆ ಕಾಮಗಾರಿಗಳನ್ನು ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರದಿಂದ ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಳ್ಳತಕ್ಕದ್ದಲ್ಲ. ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಂಡಲ್ಲಿ ಪ್ರಮಾಣ ಪತ್ರವು ಆ ಕೂಡಲೇ ರದ್ದಾಗುತ್ತದೆ.
- 5. ಕುಡಿಯುವ ನೀರು ಹಾಗೂ ಶೌಚಾಲಯಗಳಲ್ಲಿ ಸದಾ ಸ್ವಚ್ಚತೆಯನ್ನು ಕಾಪಾಡಿಕೊಳ್ಳತಕ್ಕದ್ದು ಹಾಗೂ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆಯಿಂದ ಶಾಲಾ ಕಾಲೇಜಿಗೆ ಸಂಬಂಧಿಸಿದ ಎಲ್ಲಾ ನಿರ್ದೇಶನ ಹಾಗೂ ನಿಯಮಾವಳಿಯನ್ನು ಕಡ್ಡಾಯವಾಗಿ ಪಾಲಿಸತಕ್ಕದ್ದು.

ಮೇಲೆ ತಿಳಿಸಲಾಗಿರುವ ಷರತ್ತುಗಳಿಗೊಳಪಟ್ಟು New Horizon International School, Sy. No. 115/1, Hennur Main Road, Byrathi Village, Bengaluru – 560037 ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು 2024–25ನೇ ಸಾಲಿಗೆ ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,